

# **Coconut Palm Elementary School**



Address 13601 MONARCH LAKES BOULEVARD, MIRAMAR 33027

Location Num: 3741 **Board District:** 2

**Board Member:** Torey Alston ADEFP Budget: \$3,243,215 Total Facilities Budget (Sum of Projects): \$2,700,300

# PRIMARY RENOVATIONS P.002088 Coconut Palm ES - SMART Program Renovations

**CURRENT PHASE RISK LEVEL** 

# 5B-Construction

### **PROJECT UPDATE**

- CCD 2 was issued for the PCO 15, for the descope of the 2 additional Fire alarm panels previously requested by inspector and the addition of enunciators. No shop drawings have been presented to the Building Department. PMOR has been in communication with the GC over the schedule for the additional work. - PMOR has been in communication/meetings with office of capital, team leader and FA/Electrical subcontractor due to non-payment from the General Contractor since March 2023. Subcontractor refuses to complete the work for the pending change order until payment is received. - PMOR has been in communication with the General Contractor for them to resubmit their pay application that is from April-September 2023. GC originally submitted invoice #9, and it was rejected due to documents requested from the Office of Capitals. GC was advised to resubmit. - PMOR met with GC/AE/CC regarding the issue with the backdraft dampers that were replaced and didn't need to be replace, which caused the final roof inspection to fail. GC has been stating that they will review this issue with their mechanical subcontractor. It has not been resolved, therefore, equipment tie down has not happened. PMOR/CC has been following up with the GC. - PCO 10 (GC Contract Agreement Time Extension) - was presented to CORP, but needs to be incorporated to the PCO 15 as it is related to the SOW. - PCO 14 (HVAC Curbs Reinforcing) was pending additional documents from GC for review. Roof committee, estimator and PMOR met to review the information. It was presented to CORP and approved with comments. - PMOR has been tracking the liquidated damages on the tracking table.

### **PROJECT SCOPE**

Electrical Improvements: Building 1 Fascia Repair: Buildings 1, Testing and Balancing: Buildings 1 Reroofing: Building 1

## **BUDGET**

	Current Budget	Actuals	Remaining Budget
Design	\$141,000	\$111,755	\$29,245
Construction	\$1,998,775	\$1,921,234	\$77,541
Direct Purchase	\$218,387		\$218,387
Construction Mgmt	\$283,850	\$283,850	\$0
Contingency	\$56,138		\$56,138
Consultants	\$2,150	\$1,794	\$356
Project Total:	\$2,700,300	\$2,318,633	\$381,667

# FLAG:

PHASE	2015 Q1 Q2 Q3 Q4	2016 Q1 Q2 Q3 Q4	2017 Q1 Q2 Q3 Q4	2018 Q1 Q2 Q3 Q4	2019 Q1 Q2 Q3 Q4	2020 Q1 Q2 Q3 Q4	2021 Q1 Q2 Q3 Q4	2022 Q1 Q2 Q3 Q4	2023 2024 Q1 Q2 Q3 Q4 Q1 Q2 Q3	2025 Q4 Q1 Q2 Q3 Q4	2026 Q1 Q2 Q3 Q4
PROJECT PLANNING											
HIRE DESIGNER											
PROJECT DESIGN											
HIRE CONTRACTOR											
ACTIVE CONSTRUCTION											
CONSTRUCTION CLOSEOUT											

## SCHOOL CHOICE ENHANCEMENT (SCEP)

**CURRENT PHASE BUDGET** COMPLETE \$100,000

PIP rubber surfacing, Basketball shade structure, Aiphone submaster station, Recordex, (2) AC adapters & Laptops



### TRAFFIC LIGHT SCHEDULE RISK LEVEL INDICATOR



An issue that can impact the project's budget and/or schedule, a resolution is being determined.

An issue that may result in risks, causing an impact on the project budget and/or schedule, with a resolution planned and in process.

A low-rated issue with little or no impact on the project budget and/or schedule but is still



